Specifications- 140-806-00000

Environment	Operating Temperature: 40° F/5° C to 105° F/40° C (Thermal Transfer)
	32° F/0° C to 105° F/40° C (Direct Thermal)
	Storage/Transport Environ.: -40° F/-40° C to 140° F/60° C
	Operating Humidity: 20-85% non-condensing
	Storage Humidity: 5-85% non-condensing
Electrical	Universal power supply with power-factor correction 90-264 VAC; 48-62 Hz
	Serial RS-232 and bi-directional parallel ports—with auto detect
	SB 2.0 port
Networking	ZebraNet Wireless Plus Print Server
	ZebraNet 10/100 Print Server
Resolution	203 dpi (8 dots/mm)
Memory	16 MB SDRAM
	8 MB Flash
Print width	5.04" (128mm)
Print speed	Up to 14" per second